

Tacoma Plumbing (NQ) Pty Ltd

12 Industrial Avenue STRATFORD QLD 4870 | Tel (07) 4055 1130 | Fax (07) 40581059

ABN 52 080 104 927

INSPECTION AND MAINTENANCE OF BACKFLOW PREVENTION DEVICES

Within the local authority area of: *Cairns*

City Council Cairns

Local Authority Ref or B/A no:

5013

TEST REPORT

Work Order No:

Test Certificate No: **006**

Initial Test

Retest

Standard Test

Audit Test

Owner Occupier:		Dawsons Engineering	
Address:		50 Greenbank Rd	
Suburb:	Cairns	Postcode:	4870
Contact:			
Phone:	(07) 4055,1900		
Date of Test:	<i>24/8/21</i>		
Installed By:	UNKNOWN		

Authorised Testers Name:	<i>Clint Armstrong</i>
Assessment No:	
Property Description:	
Licence No:	<i>15161071</i>
Test Kit Serial No:	<i>E1172-2-5</i>
Date Last Certified:	<i>12/8/21</i>
Place of Certification:	<i>Berric</i>

DEVICE DETAILS AND TEST RESULTS

Make of Device:	<i>Febco</i>	Size:	25	mm	Model No:	DCV	Serial No:	04879
Site Address:	50 Greenbank Rd						Asset No:	
Exact Device Location:	On the container – LHS of workshop – towards back of property							
<input type="checkbox"/>	Containment Protection	<input type="checkbox"/>	Zone Protection			<input type="checkbox"/>	Individual Protection	

	<input type="checkbox"/>	REDUCED PRESSURE ZONE DEVICE					<input type="checkbox"/>	PRESSURE TYPE VACUUM BREAKER				DOWN STREAM ISOLATION VALVE
	<input checked="" type="checkbox"/>	DOUBLE CHECK VALVE (Columns 1&2)										
	CHECK VALVE NO 1		CHECK VALVE NO 2		RELIEF VALVE	CHECK VALVE		AIR INLET				
Initial test before Maintenance	<input checked="" type="checkbox"/>	Closed Tight	<input checked="" type="checkbox"/>	Closed Tight	<input type="checkbox"/>	Opened At	<input type="checkbox"/>	Closed Tight	<input type="checkbox"/>	Opened At	<input checked="" type="checkbox"/>	Closed Tight
	<i>22</i>	KPA	<i>18</i>	KPA		KPA		KPA		KPA		KPA
	<input type="checkbox"/>	Leaked	<input type="checkbox"/>	Leaked	<input type="checkbox"/>	Not Opened	<input type="checkbox"/>	Leaked	<input type="checkbox"/>	Not Opened	<input type="checkbox"/>	Leaked
Describe Maintenance												
Parts & Materials Used												
Last Test After Maintenance	<input type="checkbox"/>	Closed Tight	<input type="checkbox"/>	Closed Tight	<input type="checkbox"/>	Opened At	<input type="checkbox"/>	Closed Tight	<input type="checkbox"/>	Opened At	<input type="checkbox"/>	Closed Tight
		KPA		KPA		KPA		KPA		KPA		KPA
	<input type="checkbox"/>	Leaked	<input type="checkbox"/>	Leaked	<input type="checkbox"/>	Not Opened	<input type="checkbox"/>	Leaked	<input type="checkbox"/>	Not Opened	<input type="checkbox"/>	Leaked
Remarks												
<input checked="" type="checkbox"/>	PASS	<input type="checkbox"/>	FAIL									

I have tested the above device, and certify it passed the performance requirements outlined in AS3500. And AS2845.3

Authorised Tester's Signature.....*Clint Armstrong*..... Date.....*24/8/21*.....